Name:

ETICAM, Inc.

Address:

2095 Newlands Drive East

P.O. Box 1075

Fernley, Nevada 89408

Contact:

Deborah L. Howard

Telephone:

(702) 575-2760

Facility Name:

ETICAM, Inc.

2095 Newlands Drive Fernley, Nevada 89408

Telephone:

(702) 575-2760

Date:

September 23, 1988

Time:

approximately 4:00 AM to 7:05 AM

Type of Incident:

Spill of effluent water and wash water from

crystallizer.

Injuries:

None

Potential Hazard:

Potential of ground contamination. Analysis indicates that there was little or no impact

to the environment.

Incident Summary:

7:05 AM on Friday September 23, 1988 a spill of water at the crystallizer, a non-hazardous waste area, was found by Jon Martin, assistant operator. The valve to the fresh water line at the crystallizer was slightly open which allowed the water to fill the crystallizer and containment area to excess capacity, which overflowed to the ground.

The excess water was pumped back into a holding vessel that was circulated back to the crystallizer. Spillage water was estimated to be approximately 200 gallons. Approximately 25 % of the water was recovered by 12:00 PM September 23, 1988.

ETICAM, Inc.
Spill September 23,1988
September 30, 1988

Incident Summary:

Notification of spill was placed at 8:50 AM on September 23, 1988 to Mr. John West of Nevada Department of Environmental Protection, by Byron B. Bradd, General Manager. The Lyon County Emergency Manager, Mr Marvin Carr was not available. Mr. Marty Jensen, North Lyon County Fire Chief was notified at 9:00 AM of the incident for Marvin Carr. Marty Jensen made a site visit at approximately 9:30 AM.

At that time soil samples from three locations were taken at six (6) inch depths within the spill area. One set of samples was retained by Marty Jensen and one set of by ETICAM for analysis (see attached results).

Corrective Measures:

Operators have been instructed to the cause of the incident, and preventive measures which should be followed.

High level sump alarm will be installed alarms will be installed by October 31, 1988 which will alert operators. Additionally it will be connected to central alarm system.

Sample ID: #1

Sample Location: Southeast corner

of contaminated area.

Matrix: Soil

Date Sampled: 09/23/88

Date Extracted: 09/26-27/88

Date Analyzed: 09/28/88

Method: EP TOX Extraction, EPA protocol

Metals 6000 Inductively Coupled Plasma

METALS:

MEIALS.	mg/L	·	
Arsenic *	<1.00		
Barium	<0.20		
Cadmium	<0.10		
Chromium	<0.50		
Lead	<0.50	1	
Mercury *	<1.00		
Selenium *	<1.00		
Silver	<0.50		•
Sodium	81.48		,
Calcium	66.70		٠
Potassium	7.99		
Magnesium	8.20		

Mercury, Arsenic, and Selenium analyzed by ICP, conformation performed with the graphic capabilities of the instrument.

Sample Id: #2

Sample Location: Southeast corner

of contaminated area.

Matrix: Soil

Date Sampled: 09/23/88

Date Extracted: 09/26-27/88

Date Analyzed: 09/28/88

Method: EP TOX Extraction, EPA protocol Metals 6000 Inductivly Coupled Plasma

METALS:

	mg/L
Arsenic *	<1.00
Barium	<0.20
Cadmium	<0.10
Chromium	<0.50
Lead	<0.50
Mercury *	<1.00
Selenium *	<1.00
Silver	<0.50
Sodium	90.51
Calcium	41.70
Potassium	20.30
Magnesium	8.50

^{*} Arsenic, Mercury, Selenium analyzed by ICP, conformation performed with ICP graphic capabilities.

Sample Id: #3

Sample Location: Southeast corner

of contaminated area.

Matrix: Soil

Date Sampled: 09/23/88

Date Extracted: 09/26-27/88

Date Analyzed: 09/28/88

Method: EP TOX Extraction, EPA protocol

Metals 6000 Inductivly Coupled Plasma

METALS:	mg/L
Arsenic * Barium	<1.00 <0.20
Cadmium	<0.10 <0.50
Chromium Lead	<0.50
Mercury *	<1.00
Selenium * Silver	<1.00 <0.50
Silver	(0.50
Sodium	81.83
Calcium	26.52
Potassium	10.04
Magnesium	10.32

^{*}Arsenic, Mercury, Selenium analyzed by ICP, conformation performed with graphic capabilites of the instrument.

Sample Id: S. Water

Sample Location: Southeast corner

of contaminated area.

Matrix: Water

METALS:

Date Sampled: 09/23/88
Date Extracted: 09/23/88

Date Analyzed: 09/23/88

Method: EPA 3050, Metals EPA 6000, Inductively Coupled Plasma

SWWM Sulfates 426C, Chlorides 407B

	mg/ L
Arsenic *	<1.00
Barium	<0.20
Cadmium	<0.10
Chromium	1.12
Lead	<0.50
Mercury *	<1.00
Selenium *	<1.00
Silver	<0.50

Sodium	11,435
Calcium	176.20
Potassium	3430
Magnesium	35.40
Sulfates	12,625
Chlorides	15,420

^{*} Arsenic, Mercury, and Selenium analyzed by ICP, conformation performed with graphic capabilites of the instrument.

Sample Id: C.Pad

Sample Location: Southeast corner

within containment area.

Matrix: Water

METALS:

Date Sampled: 09/23/88 Date Extracted: 09/23/88

Date Analyzed: 09/23/88

Method: EPA 3050, Metals EPA 6000, Inductively Coupled Plasma

SWWM Sulfates 426C, Chlorides 407B

mg/L
≪1.00
<0.20
<0.10
1.36
<0.50
<1.00
<1.00
<0.50
7,419

93.60 Calcium 2460 Potassium 33.60 Magnesium 9,667 Sulfates

13,159 Chlorides

^{*} Arsenic, Mercury, and Selenium analyzed by ICP, conformation performed with graphic capabilities of the instrument.